

To: Curry, Ron[Curry.Ron@epa.gov]; Coleman, Sam[Coleman.Sam@epa.gov]; Gray, David[gray.david@epa.gov]; Phillips, Pam[phillips.pam@epa.gov]; Crossland, Ronnie[Crossland.Ronnie@epa.gov]
From: Edlund, Carl
Sent: Mon 8/10/2015 12:34:23 PM
Subject: FW: IMG_0171.JPG

FYI...may be signs of more slugs from the mine

Sent from my Windows Phone

From: Hestmark, Martin
Sent: 8/10/2015 6:47 AM
To: Manzanilla, Enrique
Cc: Edlund, Carl
Subject: Re: IMG_0171.JPG

We believe there have been some collapses within the mine that result in upsets coming thru the treatment ponds.
Will find out more today

Sent from my iPhone

> On Aug 9, 2015, at 5:54 PM, Manzanilla, Enrique <Manzanilla.Enrique@epa.gov> wrote:
>
> So Jared is asking why the river is so dis colored at this location. Is that how it was before the accident?
>
> Sent from my iPhone
>
>> On Aug 9, 2015, at 4:03 PM, Manzanilla, Enrique <Manzanilla.Enrique@epa.gov> wrote:
>>
>> Navajo president begaye at the confluence of cement and animas.
>>
>> <IMG_0171.JPG>
>>
>>
>>
>> Sent from my iPhone